


AFBR-S50

Cover Glass Calibration: Brief Guide



This document is a short guide on the AFBR-S50 cover glass calibration procedure. For detailed information, read the full crosstalk application note, [AFBR-S50-XTK: Crosstalk Guide](#).


Calibration Procedure:

1. Check if the cover glass characteristics and mechanical design meet the following specifications.

Parameter	Value	Comment
Transmission (%)	$> 90^a$	@wavelength
Max. Thickness (mm)	≤ 2	—
Distance to Cover Material (mm)	≤ 2	Upper housing edge as reference

a. A lower value might also be possible if you do not need the maximum sensor specification.

2. Perform a test measurement with your target cover glass using the maximum target object distance and the lowest expected object remission by your application.



NOTE: If the performance is satisfactory, no calibration is needed and you are done! Otherwise, proceed with calibrating the cover glass.

3. Calibrate the cover glass by using our step-by-step guide via a terminal:
 - a. Go to <https://github.com/Broadcom/AFBR-S50-API> and clone or download the repository.
 - b. Import the project into your IDE and enable the crosstalk calibration by modifying the preprocessor definition `RUN_XTALK_CALIBRATION` from 0 to 1 in the `example.h`.
 - c. Start a terminal application (such as Putty or Termit) and establish a serial connection to the MCU controlling the AFBR-S50 sensor.
- NOTE:** With the API ported to a custom hardware (MCU), a complete porting of a UART (Tx and Rx) interface is necessary.
- d. Follow the instructions from the prompt.

```

AFBR-S50 Crosstalk Calibration
#####
#### AFBR-S50 API - Interactive Xtalk Calibration Guide #####
#####
This interactive procedure guides you through the steps needed
to compensate the application specific xtalk. A dominant source of
xtalk could be the usage of cover glasses. Please read application
note AFBR-S50-XTK-AN1xx to get more information.
#####
-----
Enter 's' to start the step-by-step xtalk calibration guide      - or -
Enter 'c' to run a continuous measurement showing binned results - or -
Enter 'x' to read the xtalk calibration table from memory       - or -
Enter 'o' to get an overview about other commands.
    
```

For further information and FAQs on the crosstalk calibration procedure, download the application note at <https://docs.broadcom.com/doc/AFBR-S50-XTK-Crosstalk-Guide>.

Copyright © 2023 Broadcom. All Rights Reserved. The term “Broadcom” refers to Broadcom Inc. and/or its subsidiaries. For more information, go to www.broadcom.com. All trademarks, trade names, service marks, and logos referenced herein belong to their respective companies.

Broadcom reserves the right to make changes without further notice to any products or data herein to improve reliability, function, or design. Information furnished by Broadcom is believed to be accurate and reliable. However, Broadcom does not assume any liability arising out of the application or use of this information, nor the application or use of any product or circuit described herein, neither does it convey any license under its patent rights nor the rights of others.

